

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 04/18/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 04/12/12 – 0700, 04/19/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
09:00	Operational status: <ul style="list-style-type: none"> <li>Observed Segment 1 of river open.</li> <li>Observed cleaning station at Perrin Dam launch site.</li> <li>Observed kiosk material placed at Perrin Dam launch site.</li> <li>Observed kayak trip down open Segment 1.</li> <li>Observed buoys removed from the confluence.</li> <li>Sheen observed at Ceresco Dam.</li> </ul>		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			